
#### SYSTEM : DEGADUR-MMA SELF LEVELLING INDUSTRIAL COATING



# **METHOD STATEMENT**

## 1. Surface Preparation

- intensive roughening and cleaning by dustfree and captive steel shot blasting using BLASTRAC machine.
- abrasive grinding by rotating tungsten carbide floor grinder at areas inaccessible to BLASTRAC machine.
- cleaning by rotating steel brush and sand dics.
- flame cleaning to remove moisture.
- vacuum clean to remove dirt and dust.

## 2. Priming

- apply DEGADUR floor sealer / Primer B71.

### 3. Top Coating

- apply DEGADUR 418 base coat by hand trowel.
- apply DEGADUR 528 top coat to non-slip and smooth finish.