


SYSTEM : DEGADUR HEAVY DUTY SELF LEVELLING AND LONG LASTING INDUSTRIAL COATING



METHOD STATEMENT

1. Surface Preparation

- intensive roughening and cleaning by dustfree and captive steel shot blasting using BLASTRAC machine.
- abrasive grinding by rotating tungsten carbide floor grinder at areas inaccessible to BLASTRAC machine.
- cleaning by rotating steel brush and sand discs.
- flame cleaning to remove moisture.
- vacuum clean to remove dirt and dust.

2. Priming

- apply DEGADUR floor sealer / Primer B71.

3. Top Coating

- apply DEGADUR 418 base coat by hand trowel.
- apply DEGADUR 525 top coat to non-slip and smooth finish.

****Option: Rough anti-skid finish is available with a broadcast of Quartz Sand.**